## CM-2030

## AC Clamp Meter(1000 Ampere)

## **Features:**

- $3^{1}/_{2}$  MANUAL AC CLAMP METER.
- FULLY PROTECTED in the RANGE
- CLAMP OPEN: 52mm.
- Clamp Torch.





## **Technical data:**

Function	Range	Resolu			Accuracy
DC VOLTAGE (DCV)	1000V	1V			<u>+(0.8%+2)</u>
AC VOLTAGE (ACV)	750V	1V			<u>+(1.0%+5)</u>
AC Current (ACA)	200A	0.1A		LA	<u>+(</u> 3.0%+5)
AC Current (ACA)	1000A	1A			
	200 Ω	0.1 Ω		LΩ	<u>+(1.0%+3)</u>
Resistance $(\Omega)$	20k Ω	10 Ω		Ω	
	200k Ω	100 Ω		0 Ω	
	Description			Test Condition	
Diode and Continuity	Diode forward voltage drop.			Forward DC Current is approx 1mA, Reserve DC voltage is less than 3V.	
	When resistance is less then $30\pm10 \Omega$ , buzzer sounds		Open circuit voltage is about 3V		

• Standard Accessories : Soft Carrying case, Manual, Probe

• Dimension

: 123(H) x270(W) x 35(D)mm

